

<b>SERVICEHÄNDBOK</b>	GIVARE	C-G1.03s
<b>VARME</b>		
<b>VENTILATION</b>	MOTSTÄNDSTABELL PLATINA 100 Ohm/0 °C	Pt 100

°C	Ohm	°C	Ohm	°C	Ohm	°C	Ohm
0	100.0	60	123.2	150	157.3	300	211.8
2	100.8	62	124.0	155	159.1	305	213.6
4	101.6	64	124.8	160	161.0	310	215.3
6	102.3	66	125.5	165	162.9	315	217.1
8	103.1	68	126.3	170	164.7	320	218.8
10	103.9	70	127.1	175	166.6	325	220.6
12	104.7	72	127.8	180	168.4	330	222.3
14	105.5	74	128.6	185	170.2	335	224.1
16	106.2	76	129.4	190	172.1	340	225.8
18	107.0	78	130.1	195	173.9	345	227.6
20	107.8	80	130.9	200	175.8	350	229.3
22	108.5	82	131.7	205	177.6	355	231.1
24	109.3	84	132.4	210	179.4	360	232.8
26	110.1	86	133.2	215	181.2	365	234.5
28	110.9	88	133.9	220	183.1	370	236.2
30	111.7	90	134.7	225	184.9	375	238.0
32	112.4	92	135.5	230	186.7	380	239.7
34	113.2	94	136.2	235	188.5	385	241.4
36	114.0	96	137.0	240	190.3	390	243.2
38	114.8	98	137.7	245	192.1	400	246.6
40	115.5	100	138.5	250	193.9	410	250.0
42	116.3	105	140.4	255	195.7	420	253.5
44	117.1	110	142.3	260	197.5	430	256.9
46	117.9	115	144.2	265	199.3	440	260.3
48	118.6	120	146.1	270	201.1	450	263.7
50	119.4	125	147.9	275	202.9	460	267.0
52	120.2	130	149.8	280	204.7	470	270.4
54	121.0	135	151.7	285	206.5	480	273.8
56	121.7	140	153.5	290	208.2	490	277.1
58	122.5	145	155.4	295	210.0	500	280.4